



Models Affected:
Linea - 4 GROUP
FB-70 - 4 GROUP

TECHNICAL BULLETIN #24

June 27, 2001

This Technical Bulletin is being sent to all field service technicians installing new La Marzocco Espresso Machines.

Due to vibration during shipping, the L500 contactor screws may become loose.

ACTION: All field service technicians should check to ensure that the screws on the L500 contactor are tight prior to connecting (see figure below).

