

Models Affected:
Linea 4AV - ALL
Linea 3AV - ALL



TECHNICAL REFERENCE 110200/17

LINEA(USA) TECHNICAL BULLETIN

November 2, 2000

The fastening method for the Linea Surround has been changed. A spring nut has been used to replace the tapped holes as indicated in the figure below. In place of the tapped hole, a 1/4" through hole is drilled and the spring nut is installed.

La Marzocco does not recommend that modification be performed however, if a customer does wish to make this modification the vendor information appears in the figure below.

