



**la marzocco**

handmade in florence

# Mazzer Technical Bulletin #01

Grid (mesh)

6/4/2015

Due to reports of static generated when grinding and for a limited quantity of Major Electronic only, Mazzer has fitted a different grid (mesh) with 12 holes.

Mazzer has found that with some coffee beans, the grid (mesh) with 12 holes might (but not necessarily will) clog the duct specifically when set a bit coarser than espresso. As a result, Mazzer has returned to the previous grid with 10 holes.

This issue affects Major Electronic grinders from 143000 to 1517000. To resolve this issue on existing grinders, we will be providing 10-hole grids, and replacement gaskets.

Please contact [Solutions@lamarzoccousa.com](mailto:Solutions@lamarzoccousa.com) for replacement parts.

Thanks,  
La Marzocco Product Management Team

Do not hesitate to contact us for further questions:  
[Solutions@lamarzoccousa.com](mailto:Solutions@lamarzoccousa.com)