

Models Affected:  
Linea - ALL  
FB-70 - ALL



TECHNICAL REFERENCE 071101/25

## TECHNICAL BULLETIN #26

November 26, 2001

### PART RECALL

La Marzocco International has found a feature on part number TL27 that is out of tolerance (please see figure below). Our spare part distributors may have received several of these parts. Please check all TL27 tubes for the out of tolerance feature shown below. All out of tolerance tubes should be returned to La Marzocco International. In the figure below Detail A shows the correct feature. Detail B shows the out of tolerance feature.

