

TECHNICAL BULLETIN #32 June 29, 2007

TECHNICAL REFERENCE: 062907/32


MODEL/S AFFECTED: GB/5 and FB/80 models since the machine serial number 0500 - ALL PART/S DESCRIPTION: new 16 pin ribbon cable wing connector and push button bottom box

La Marzocco replaced the 16 pin ribbon cable connector with a new updated model.

The new connector is equipped with two wing clips on the sides to ensure the connection between the cable and the female connector.

Consequently the back plastic box cover (EE model-E.1.007) for the manual brew switch has been modified with a larger slot to accomodate the new connector.

The modification does not affect the rest of the GB/5 & FB/80 AV model key pad boxes.



The following is a kit description:




HANDMADE IN FLORENCE


TECHNICAL BULLETIN #32

TECHNICAL REFERENCE: 062907/32

June 29, 2007


MODEL/S AFFECTED: GB/5 and FB/80 manual brew button connection – ALL PART/S DESCRIPTION: new 16 pin ribbon cable wing connector and push button back box cover





Previous version until s/n 0499

LAD3D5/C0*



16 pin ribbon cable complete with wing connector: LAD3D5/CO4 - 80 cm ribbon cable

LAD3D5/CO5 - 110 cm ribbon cable

LAD3D5/CO6 - 140 cm ribbon cable

New kit and actual version used on machines from s/n 0500 which will include the back box cover with a larger slot for the new connector size and the following new wing connector parts:

